

RISK REMINDER

Winter Three-Point Contact Tips

Maintain **Three-point contact** to help prevent slips, trips, and falls, when entering or exiting snowplow equipment, especially during snow and ice conditions. This means having **two hands and one foot** or **two feet and one hand** in contact with the vehicle at all times.









Face the Vehicle: Always face the vehicle/equipment when climbing in or out.

Use Handholds and Steps: Ensure you use the designated handholds and steps.

Avoid Carrying Items: Keep your hands free to maintain contact points.

Check for Ice: Be extra cautious of icy surfaces on steps and handholds.

Wear Proper Footwear: Use boots with good traction to reduce the risk of slipping.

Clear Snow and Ice: Regularly clear snow and ice from steps and handholds.

SLOW DOWN!: Take your time getting in and out of trucks and equipment.