



PARTNERING WITH TOWNSHIPS

TOWNSHIP OFFICIALS OF ILLINOIS RISK MANAGEMENT ASSOCIATION

# RISK REMINDER

## What's Wrong With This Picture?



This month's risk reminder is a contest between contractors. This is a photograph of a recently visited site. The ladder is being used by a carpenter contractor to access work within the trusses and to install roof sheathing.

What OSHA regulations have been violated?  
What is the proper method of abatement?

For more information, contact your Loss Control Consultant at (800) 252-5059, ext. 1387 or 1384.

CLAIM REPORTING HOTLINE (844) 562-2720 | Available 24/7