



PARTNERING WITH TOWNSHIPS

TOWNSHIP OFFICIALS OF ILLINOIS RISK MANAGEMENT ASSOCIATION

# RISK REMINDER

## What's Wrong With This Picture?



This month's risk reminder is a contest between contractors. This is a photograph of a recently visited site. The ladder is being used by a carpenter contractor to access work within the trusses and to install roof sheathing.

What OSHA regulations have been violated?  
What is the proper method of abatement?

**For more information, contact your Loss Control Consultant at (888) 562-7861**

CLAIM REPORTING HOTLINE (844) 562-2720 | Available 24/7